

SERVICE BULLETIN

Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines

ATA System: 72-00-00 Engine

**HIGHLY
RECOMMENDED***

*Failing to comply with the instructions of this SB may result in improper operation of the engine.

1) Planning information

1.1) Applicability

All versions of the engine type:

Engine type	Serial number
912 ULS (Series)	all

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin SB-912-079, latest edition section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

Symbols used For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX' scope of responsibility.

In any case the original text in English language and the metric units are authoritative.